



ITxPT Vehicle Labeling Report

REPORT ID	201742-01-DC1
DATE	2018/06/05
COMPANY (<i>manufacturer</i>)	IVECO
TESTER	ITxPT laboratory manager
SPECIFICATION	S01 - v2.0.1
TOOLS USED FOR THE TEST	ITxPT Mobile Laboratory



Vehicle configuration tested by ITxPT laboratory

Bodywork manufacturer	Chassis manufacturer	Vehicle concept	Vehicle bodywork	Model	Euro level	Engine type	Length	DC
IVECO BUS	IVECO BUS	Coach	Coach	Magelys proto	Euro 6	Diesel C9	12,2m	

Vehicle configuration included in the label as declared by vehicle manufacturer

Bodywork manufacturer	Chassis manufacturer	Vehicle concept	Vehicle bodywork	Model	Euro level	Engine type	Length	DC
IVECO BUS	IVECO BUS	Coach	Coach	Magelys	Euro 6	Diesel C9	12,2m	<u>DC1</u>
IVECO BUS	IVECO BUS	Coach	Coach	Magelys	Euro 6	Diesel C9	12,8m	<u>DC1</u>

COMMENT	<p>The tests V-037, V-040, V-041, V-042 related to Audio interface are not compliant.</p> <p>Vehicle manufacturer commits that all mandatory tests compliant for the vehicle configuration tested are the same implemented in all vehicle configurations declared as included in the label. Vehicle manufacturer shall declare the list of compliant optional test implemented for each vehicle configuration included in the label.</p> <p>Vehicle manufacturer shall declare any change impacting the result of one or several tests for each vehicle configuration using the "declaration of change" file available on ITxPT documentation center.</p>
----------------	--

